Oil Field Environmental Incident Summary

Responsible Party: SM Energy Company **Well Operator:** SM ENERGY COMPANY

Well Name: LEININGER 4-27H

Field Name: COLGAN Well File #: 22793

Date Incident: 7/14/2014 Time Incident: 06:30 Facility ID Number:

County: DIVIDE Twp: 163 Rng: 101 Sec: 27 Qtr: NW NW

Location Description:

Submitted By: Luke Studer Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	2	Barrels	2	Barrels	2	barrels	
Brine	3	Barrels	3	Barrels	3	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/11/2015 Clean Up Concluded: 7/14/2014

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Lease Operator shut the valves on the bottom site glass and the leak stopped.

Wastes Disposal Location: Recovered oil put back in tank. Recovered SW and contaminated soil

to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 7/17/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.